Manufacturer name:	Phillips Respironics
About the Recall:	All devices are required to have a mandatory Software update to version 1.05.10.00: 1. Accuracy of Oxygen Delivery (2022-CC-SRC-049) 2. Environmental Contamination of device sensor (2023-CC-SRC-003) 3. Battery Deletion of loss of Power Alarms Triggered (2024-CC-SRC-001) 4. Incomplete Contraindications Statement (2023-CC-SRC-001) 5. Translation errors in the Korean, Traditional Chinese, and Spanish Instructions for Use (IFU) manuals (2023-CC-SRC-006) 6. Flow Sensor Reading Compensation 7. Software Alarm Errors 8. Labeling-Related Issues-Ozone-Based Disinfection Method **Hazard/harm associated with this issue:** Barotrauma, Hypoventilation/hypercapnia and rebreathing of excessive C02, Hypoventilation/Hypercapnia (AVAPS used invasively) Non-Safety impacted fixes: 1. Update to HIP/LIP-HEP/LEP technical alarm 2. Added priority Vent Service Required Alarm detecting contamination on flow sensor 3. Update to address E110 Vent INOP triggered by motor stalls

	4. Update to spontaneous breath percentage calculation 5. Updates to floating points calculations 6. Updates to translation strings to avoid confusion for customers 7. Update to address used interfaces issues 8. Adjustment of maximum alarm volume setting to meet standard requirements 9. Additional fixes to address software errors, as well as data corruption and transfer of data with Care Orchestrator and Care Orchestrator Essence
Products(s) numbers/models that are affected:	Trilogy EVO, Trilogy EVO 02, and Trilogy EV300 ventilators
URL Link(s) to Manufacturer Notice/Web Site:	www.healthcare.philips.com 1-800-345-6443
Actions to be taken by customer/Patient:	If you have any questions regarding this Urgent Medical Device Recall notice, please contact your home care provider or contact Philips Respironics directly.