

<b>Manufacturer name:</b>	Cardinal Health																				
<b>About the Recall:</b> <i>Clear overview of recall and products affected</i>	Cardinal Health Monoject™ Enteral Syringes with ENFit (6, 12, 35, 60 mL) have demonstrated recognition and compatibility issues with certain syringe enteral feeding pumps.																				
<b>Please list the specific products(s) numbers/model s that are affected:</b>	<table border="1"> <thead> <tr> <th data-bbox="467 541 565 583">MMS #</th> <th data-bbox="570 541 727 583">MFG Catalog #</th> <th data-bbox="732 541 1263 583">Description</th> <th data-bbox="1268 541 1414 583">Affected Lot(s)</th> </tr> </thead> <tbody> <tr> <td data-bbox="467 590 565 653">1055381</td> <td data-bbox="570 590 727 653">406SE</td> <td data-bbox="732 590 1263 653">SYRINGE, ENTERAL W/ENFIT CONN STR PUR 6ML (100/BX 4BX/CS)</td> <td data-bbox="1268 590 1414 653">230503 230701</td> </tr> <tr> <td data-bbox="467 659 565 722">1055383</td> <td data-bbox="570 659 727 722">412SE</td> <td data-bbox="732 659 1263 722">SYRINGE, ENTERAL W/ENFIT CONN STR PUR 12ML (80/BX 6BX/CS)</td> <td data-bbox="1268 659 1414 722">230501 230502 230601</td> </tr> <tr> <td data-bbox="467 728 565 791">1055384</td> <td data-bbox="570 728 727 791">435SE</td> <td data-bbox="732 728 1263 791">SYRINGE, ENTERAL W/ENFIT CONN STR PUR 35ML (40/BX 4BX/CS)</td> <td data-bbox="1268 728 1414 791">230501 230601 230602</td> </tr> <tr> <td data-bbox="467 798 565 861">1055385</td> <td data-bbox="570 798 727 861">460SE</td> <td data-bbox="732 798 1263 861">SYRINGE, ENTERAL W/ENFIT CONN STR PUR 60ML (30/BX 4BX/CS)</td> <td data-bbox="1268 798 1414 861">230501 230701 230702</td> </tr> </tbody> </table>	MMS #	MFG Catalog #	Description	Affected Lot(s)	1055381	406SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 6ML (100/BX 4BX/CS)	230503 230701	1055383	412SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 12ML (80/BX 6BX/CS)	230501 230502 230601	1055384	435SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 35ML (40/BX 4BX/CS)	230501 230601 230602	1055385	460SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 60ML (30/BX 4BX/CS)	230501 230701 230702
MMS #	MFG Catalog #	Description	Affected Lot(s)																		
1055381	406SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 6ML (100/BX 4BX/CS)	230503 230701																		
1055383	412SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 12ML (80/BX 6BX/CS)	230501 230502 230601																		
1055384	435SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 35ML (40/BX 4BX/CS)	230501 230601 230602																		
1055385	460SE	SYRINGE, ENTERAL W/ENFIT CONN STR PUR 60ML (30/BX 4BX/CS)	230501 230701 230702																		
<b>URL Link(s) to Manufacturer Notice/Web Site:</b>	CardinalHealth.com																				
<b>Actions to be taken by customer/Patient:</b>  <i>Please include phone numbers and emails when applicable</i>	<p>Immediately discontinue use of any product matching the affected item(s) and lot number(s) listed in the item table. If you have no products matching the affected item(s) and lot number(s), no further action is needed.</p> <p>For questions related to this notification and/or acknowledgement form that are not adequately addressed, please contact the market action team at: GMB-FieldCorrectiveAction@cardinalhealth.com or call 800-292-9332.</p>																				