

Manufacturer name:	Nestle Health Science			
About the Recall:	Nestle recently completed an investigation following complaints of sporadic leakage during use on five lots of their UltraPak 1500 ML Spike products. The integrity of the pouches is not compromised, and commercial sterility is maintained, but once spiked, the product may flow through an unsealed port fitment on the pouch. This issue does not pose a food safety risk but does not meet Nestle quality standards.			
Products(s)	MMS#	MFG Catalog #	Description	Affected Lot(s)
numbers/models that are affected:	804537	10043900365838	DIABETISOURCE AC SPIKE RT PLUS1500ML (4/CS)	5010572151 5017572151 5018572151
	800074	10043900185832	FIBERSOURCE HN, SPIKERIGHT PLUS 1500ML (4/CS)	5025572151 5027572151
URL Link(s) to Manufacturer Notice/Web Site:	Nestlehealthscience.com			
Actions to be taken by customer/Patient:	Immediately discontinue use of any product matching the affected item(s) and lot number(s) listed above. If you have no product matching the affected item(s) and lot number(s), no further action is needed			
	If you have any issues or have the listed product in your supply, please contact Nestle Health Science for replacement.			

Nestle Health Science may be reached by calling (877) 463-7853 Your safety is our top priority. Thank you for your attention to this matter.