

<b>Manufacturer name:</b>	Avanos Medical, Inc																																					
<b>About the Recall:</b> <i>Clear overview of recall and products affected</i>	An Urgent Medical Device Recall regarding specific lots of their BALLARD* Closed Suction System for Adults, 14 Fr, DSE, MDI. This notice has been issued because These lots were labeled as not being made with Di(2-ethylhexyl) phthalate (DEHP); however, Avanos has determined that the tubing components of the product did contain DEHP.																																					
<b>Please list the specific products(s) numbers/models that are affected:</b>	<table border="1"> <thead> <tr> <th data-bbox="472 552 558 590">MMS #</th> <th data-bbox="558 552 686 590">MFG Catalog #</th> <th data-bbox="686 552 987 590">Description</th> <th colspan="4" data-bbox="987 552 1417 590">Affected Lot(s)</th> </tr> </thead> <tbody> <tr> <td data-bbox="472 590 558 741" rowspan="6">364042</td> <td data-bbox="558 590 686 741" rowspan="6">221038</td> <td data-bbox="686 590 987 741" rowspan="6">TRACH, DBL SWIVEL W/ADPTR 14FR12" (20/CS)</td> <td data-bbox="987 590 1089 617">30112716</td> <td data-bbox="1089 590 1192 617">30117487</td> <td data-bbox="1192 590 1294 617">30117633</td> <td data-bbox="1294 590 1417 617">30119102</td> </tr> <tr> <td data-bbox="987 617 1089 644">30122936</td> <td data-bbox="1089 617 1192 644">30126227</td> <td data-bbox="1192 617 1294 644">30127494</td> <td data-bbox="1294 617 1417 644">30151042</td> </tr> <tr> <td data-bbox="987 644 1089 672">30116495</td> <td data-bbox="1089 644 1192 672">30117488</td> <td data-bbox="1192 644 1294 672">30113925</td> <td data-bbox="1294 644 1417 672">30116223</td> </tr> <tr> <td data-bbox="987 672 1089 699">30122179</td> <td data-bbox="1089 672 1192 699">30124946</td> <td data-bbox="1192 672 1294 699">30137504</td> <td data-bbox="1294 672 1417 699">30194152</td> </tr> <tr> <td data-bbox="987 699 1089 726">30116496</td> <td data-bbox="1089 699 1192 726">30117632</td> <td data-bbox="1192 699 1294 726">30119101</td> <td data-bbox="1294 699 1417 726">30123991</td> </tr> <tr> <td data-bbox="987 726 1089 741">30124942</td> <td data-bbox="1089 726 1192 741">30127429</td> <td data-bbox="1192 726 1294 741">30153170</td> <td data-bbox="1294 726 1417 741"></td> </tr> </tbody> </table>				MMS #	MFG Catalog #	Description	Affected Lot(s)				364042	221038	TRACH, DBL SWIVEL W/ADPTR 14FR12" (20/CS)	30112716	30117487	30117633	30119102	30122936	30126227	30127494	30151042	30116495	30117488	30113925	30116223	30122179	30124946	30137504	30194152	30116496	30117632	30119101	30123991	30124942	30127429	30153170	
MMS #	MFG Catalog #	Description	Affected Lot(s)																																			
364042	221038	TRACH, DBL SWIVEL W/ADPTR 14FR12" (20/CS)	30112716	30117487	30117633	30119102																																
			30122936	30126227	30127494	30151042																																
			30116495	30117488	30113925	30116223																																
			30122179	30124946	30137504	30194152																																
			30116496	30117632	30119101	30123991																																
			30124942	30127429	30153170																																	
<b>URL Link(s) to Manufacturer Notice/Web Site:</b>	<a href="http://avanos.com">avanos.com</a>																																					
<b>Actions to be taken by customer/Patient:</b>  <i>Please include phone numbers and emails when applicable</i>	<p>Immediately discontinue use of any product matching the affected item(s) and lot number(s) listed above.</p> <p>For questions regarding this notification, please contact Avanos via email at <a href="mailto:fieldactioncare@avanos.com">fieldactioncare@avanos.com</a>.</p>																																					